

M645 SUPER

7 ACCESSORY (Connector N)

7 TECHNICAL BULLETIN

NEW CONTACTS FOR CONNECTOR N


1/1

2

OUR REF.NO 040

- 1. CAUSE : Contact B,C, and D : Weakened.
- 2. MODIFICATION : Material of contact B,C, and D : Changed.
- 3. MODIFICATION DATE : Since 1987 March production.

New P/No. 6284 86562 Contact D
 6284 86582 Contact B
 6284 86572 Contact C



Remarks

24 FEB 87

Vertical text on the right edge of the page.

NEW RELEASE PLATE FOR AUTO BELLOWS

1/2


OUR REF.NO. 021


1. CAUSE : Release plate(type 1) does not push the release button of body.

2. MODIFICATION : Shape of release plate.

3. MODIFICATION DATE : From October, 1986.

4. REPAIR STEP : Replacement of release plate (type 2)





Remarks